

# Testdruck

!"#$%&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£
"#$%&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥
#$%&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§
$%&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§f
%&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§fø
&'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâ
'()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâê
()*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêô
)*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôû
*+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûá
+,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáé
,-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéó
-./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóú
./0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúà
/0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàè
0123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèò
123456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòù
23456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùä
3456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäë
456789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäëö
56789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäëöü
6789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäëöüÅ
789:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäëöüÅî
89:;<=>?@ABCDEFGHIJKLMNOPQRSTUVWXYZ[\]^_‘abcdefghijklmnopqrstuvwxyz{|}~▒ÀÂÈÊËÎÏ´`^¨˜ÙÛ£¯Ýý°ÇçÑñ¡¿¤£¥§føâêôûáéóúàèòùäëöüÅîØ


ABC



0% 50% 100%



0% 50% 100%



| 1 | 2 | 3 | 4 | 5 | 6 |
| --- | --- | --- | --- | --- | --- |
| | | | | | |

# MAINTENANCE

Print Date:17/11/26

## MFC-L6900DW series

Serial No.=E75407H8N843690 Model=8C5-J98 Country=0D03 SW CheckSum=A7 /NG

Main ROM: Ver.ZQ U2109240227
Sub ROM: Ver.1.54 P2109080218
Boot ROM: B1708170949
Engine Version: 2.17
LT1 Main ROM: _
LT2 Main ROM: _
TT Main ROM: _
Memory Version: a

ROM ChkSum: D74A
RTC Check: OK
RTC BackUp: OK
Before BackUp: 00:17
After BackUp: 11:17

USB Prod.ID: 03B0
RAM Size = 1024Mbyte

OK 000000 0404 OKOK0100000000001
C018000000010010
0000200070600010 00000090

00000000 00000109 00000000 00000000
00000000 00000000 00000000 00000000
00000000 00000000 00000000 00000000

## Remaining life of :

*Toner Cartridge: 81%
**Drum Unit: 39%
Fuser Unit: 199972 (100%)
Laser Unit: 159213 (80%)

Toner Warn Threshold: OFF
PF Kit MP: 49999 (100%)
PF Kit 1: 165926 (83%)

PF Kit 2: 200000 (100%)
PF Kit 3: 200000 (100%)
PF Kit 4: 200000 (100%)
PF Kit 5: 200000 (100%)

<Device Status(Total/2-sided)>
Total Page Count: 40787/13433
Copy Count: 10010/4557
PC-Print Count: 30728/8874
FAX Count: 0/0
Other Count: 49/2

***Average Coverage(Total): 3.61%
***Average Coverage(Current)*: 4.23%
***Average Coverage(Previous): 3.60%
***Average Coverage(Latest): 2.01%

<Drum Information>
Drum Page Count: 61897
Drum Count: 364575

<Developing Roller Count(Current/Previous)>
38913/228281

<Total Pages Printed>

| | |
|---|---|
| MP Tray: 1 | 2-sided: 6714 |
| Tray 1: 34074 | Tray 2: 0 |
| Tray 3: 0 | Tray 4: 0 |
| Tray 5: 0 | Std.Output: 34068 |
| A4/Letter: 40752 | Envelope: 16 |
| Legal/Folio: 16 | A5: 0 |
| B5/Executive: 1 | Others: 2 |

Plain/Thin/Recycled: 40786
Thick/Thicker/Bond: 0
Envelope/Env.Thick/Env.Thin: 1

| | |
|---|---|
| Colour 0 | Letterhead 0 |
| Label: 0 | Hagaki: 0 |

Toner(Current/Previous): 3863/22855
Developing Roller Count(Current/Previous)
38663/227470

<Total Paper Jams: 17>

| | |
|---|---|
| Jam MP Tray: 0 | Jam Inside: 3 |
| Jam Tray 1: 13 | Jam Rear: 1 |
| Jam Tray 2: 0 | Jam 2-sided: 0 |
| Jam Tray 3: 0 | Jam Tray 4: 0 |
| Jam Tray 5: 0 | |

<Fax Count>
Fax TX Count: 0

<Function Info: 0000800002 0000200000>

<Error History (last 10 errors)>

| | | Page | (C) | % |
|---|---|---|---|---|
| 1: 9309:No Paper | 17/11/26 11:17 | 40785 | 21 | 27 |
| 2: 1F00:Print Unable 1F | 04/11/26 12:24 | 40779 | 20 | 43 |
| 3: 1808:Print Unable 18 | 04/11/26 12:23 | 40779 | 20 | 42 |
| 4: 9309:No Paper | 01/01/16 00:00 | 40774 | 14 | 43 |
| 5: 4C01:Replace Toner | 10/04/26 14:58 | 36923 | 25 | 23 |
| 6: 9309:No Paper | 09/04/26 13:40 | 36844 | 24 | 22 |
| 7: A200:Document Jam | 17/03/26 13:33 | 34886 | 22 | 24 |
| 8: 9309:No Paper | 27/02/26 09:45 | 34495 | 23 | 23 |
| 9: A300:Document Jam | 18/11/25 10:05 | 32521 | 26 | 27 |
| 10: 9309:No Paper | 05/11/25 11:47 | 32049 | 26 | 29 |

<Replace Count>
Toner Cartridge: 3 (0) 13/04/26

| | | |
|---|---|---|
| Drum Unit: 0 | Fuser Unit: 1 | Laser Unit: 0 |
| PF Kit MP: 0 | PF Kit 1: 0 | PF Kit 2: 0 |
| PF Kit 3: 0 | PF Kit 4: 0 | PF Kit 5: 0 |

<Scan Count>

| | |
|---|---|
| SX Page Count: 4989 | 2-sided Page Count: 4662 |
| FB Page Count: 2958 | Scanner Page Count: 4452 |
| ADF Jam: 14 | |
| ADF Jam SX: 11 | ADF Jam 2-sided: 3 |

<COM Error>
1: FFFF00DF 15/07/25 08:30
2: BF010000 04/06/25 13:37
3: 11070000 04/06/25 13:32

<Developing Bias: 399V>

<Engine Sensor Log>

| | |
|---|---|
| KO: 000115/001040 | MN: 000485/001085 |
| RS: 000610/001085 | EJ: 001205/001105 |

<Status Log>
012001 830B03 83F603 012001 830100
830300 012001 012001 012001 830100

<HP ME/HP ME Log>
0/00:00:00:00:00:00:00:00:00:00:00:00:00:00:00:00

<Temperature/Humidity>
Temperature: 21 degrees(C) (MAX: 32 MIN: 12)
Humidity: 26% (MAX: 75 MIN: 8)

<Power On Time: 38903 hours>
<Power On Count: 31>

<First Date PC-Prn: 19/01/22 / RTC: 19/01/22>

<Last Media Type: Plain>

1:4,0,59,62,52,62,52,335,0
2:4,0,66,62,52,61,52,329,0
3:3,0,61,175,52,334,0,0,0

* Remaining life will vary depending on the types of documents printed, their coverage and device usage.

** Based on A4/Letter printing.

*** Calculated coverage.